r23.1.3 Changelog

```
+----------------------------------+
|   r23.1.3 Release - 97965
+----------------------------------+
```

Release day 25th January 2022

Fixes

- DSOF-21313 - Fixed an issue where machines with bluefish cards could spontaneously restart
- DSOF-22986 - Fixed an issue where launching designer would always trigger "VFC outputs may be in an inconsistent state"
- DSOF-23008 - Fixed an issue where live update could become blocked and changes would not propagate through the session
- DSOF-23095 - Fixed an issue where vx4 and vx4+ video inputs do not update when switching Capture Card Variant to Matrox